

100




FIG. 1




FIG. 2




FIG. 3A

FIG. 3B




FIG. 3B

FIG. 3C




FIG. 3C





FIG. 4A

$$C_{k,m-1} = \begin{bmatrix} C_{0,0} & C_{0,1} & \cdots & C_{0,m-1} \\ & \cdot & & \\ C_{1,0} & & \cdot & \\ & & & \cdot \\ C_{2,0} & & & & \cdot \\ & & & & & \cdot \\ \vdots & & & & & & \cdot \\ & & & & & & & \cdot \\ C_{k,0} & & & & & & & & C_{k,m-1} \end{bmatrix}$$

FIG. 4B



*PSK Fast Hadamard Transform*

FIG. 5





FIG. 6



800




FIG. 8